















C011 ASSEMBLY INSTRUCTION

Ax1 	Fx1  M6*25mm	1 	2 
Bx1 	Gx4  M6x50mm	3 	4 
Cx1 	Hx3  M6x35mm	5 	
Dx1 	Ix2  M6x16mm		
Ex1 	Jx1 